






CX4 CLEARCOAT

2K Express Air Dry Fast Clearcoat

ACTIVATORS	BAKE TIME	TEMPERATURE
 <p style="margin-left: 20px;">HX 4 <i>2K Express Air Dry Hardener</i></p>	10 min	60 degrees
 <p style="margin-left: 20px;">HS 10 <i>2K Fast Hardener</i></p>	10 – 15 min	
 <p style="margin-left: 20px;">HS 25 <i>2K Normal Hardener</i></p>	15 – 20 min	